## Sensor Mounting

The optoNCDT 1900 sensor is an optical system for measurements with micrometer accuracy. Pay attention to careful handling during mounting and operation.

- Mount the sensor only to the existing through-holes (mounting holes) on a flat surface. Clamps of any kind are not permitted.
- Mount the sensor by means of 2 screws type M4 or by means of through bores for M3 with the screws from the accessories.

# Measuring Range, Start of Measuring Range



1) For displacement values without zero setting or mastering

Sensor mounting with diffuse reflection. The laser beam must be directed perpendicularly onto the surface of the target, otherwise measurement uncertainties cannot be excluded.

Digital value<sup>1</sup> MR = Measuring range 5.2 V / 10.2 V 262077 SMR = Start of measuring range MMR = Mid of measuring range 98232 EMR = End of measuring range

∕/₩

min 10



MR	2/2LL	6/6LL	10/10LL	25/25LL	50/50LL	100	200	500
SMR	15	17	20	25	40	50	60	100
X	23	27	33	33	36	37	39	43
Y	3	9	14	33	45	75	130	215

Dimensions in mm



connector



# Direct fastening



M3 x 40: ISO 4762, A2-70

Mounting

Bolt connection



M4: ISO 4762, A2-70 screw depth min. 10 mm



Dimensional drawing, drilling pattern, mounting plate Alignment via centering elements (optional)

#### Pin Assignment



Tx +

Rx +

Tx -

ILD1900 / ILD1900LL with open ends

ILD1900 / ILD1900LL with pigtail

	Pin	Cable color PC1900-x	Description
	5	Red	Supply voltage (11 30 VDC)
	14	Blue	System ground supply, switch signals (Laser on/off, Zero, Limits)
		Coaxial inner	Current 4 20 mA ( $R_{\rm B}$ < ( $V_{+}$ - 6 V) / 20 mA))
utput 1		conductor, white	Voltage 0 5 VDC Voltage 0 10 VDC (R <sub>i</sub> = 50 Ohm, I <sub>max</sub> = 5 mA)
	2	Screening, black	Reference potential for analog output
off	3	Black	Switching input, Laser operates when pin 3 is connected to GND
tion input	13	Violet	Switching input, TrigIn, Zero/Master, TeachIn, SlaveIn
it 1	10	Brown	Switching output 1
	11	White	Switching output 2 Programmable switching behavior: (NPN, PNP, push-pull)
	17	Gray-pink	Symmetrical synchronous output (Master) or input (Slave). RS422 level, 120 Ohm switchable for terminating
	12	Red-blue	selectable input or output depending on synchronization mode
	8	Gray	RS422 - Output
	15	Pink	(symmetric) terminate receiver with 120 Ohm
	9	Green	RS422 - Input
	16	Yellow	(symmetric) internally terminated with 120 Ohm



\_\_\_\_10 \_\_\_\_9 The PC1900 sensor cable is qualified for drag chain use. One end of the cable has a molded cable connector, the other end has braids with ferrules.

17-pin plug-in connector, M12, pin side of pigtail cable

#### Supply voltage, Nominal value: 24 V DC (11 ... 30 V, P < 3 W)

5    0	Sensor Pin	PC1900-x/Y Color	Supply
ILD1900	5	Red	<i>V</i> <sub>+</sub>
	14	Blue	GND

Use supply voltage for measurement instruments only. MICRO-EPSILON recommends using an optional available power supply unit PS2020 for the sensor

with shield

Overall shield

PC1900-x with open ends

#### Laser Safety

The optoNCDT 1900 operates with a semiconductor laser with a wavelength of 670 nm (visible/red) or 658 nm (visible/red). Operation of the laser is indicated visually by the LED state on the sensor. During operation of the sensor, the pertinent regulations according to IEC 60825-1 on "Safety of laser products" must be fully observed at all times. The sensor complies with all applicable laws for the manufacturer of laser devices. Please observe national regulations, e.g., Laser Notice No. 50 for the USA.

If both warning labels are covered over when the unit is installed, the user must ensure that supplementary labels are applied.

Observe the national laser protection regulations.

#### Laser Class 2

The sensors fall within laser class 2. The laser is operated on a pulsed mode, the maximum optical power is  $\leq$  1 mW. The pulse frequency depends on the adjusted measuring rate (0.25 ... 10 kHz). The pulse duration of the peaks is regulated depending on the measuring rate and reflectivity of the target and can be 4 up to 3995  $\mu$ s.

beam hits the eve.

Laser radiation. Irritation or

injury of the eyes possible. Use

suitable protective equipment

and close your eyes or imme-

diately turn away if the laser

the eve.

Laser radiation. Irritation or

injury of the eyes possible.

Close your eyes or immediately

turn away if the laser beam hits



Laser warning sign on the sensor housing

## Laser Class 3R

LASER RADIATION DO NOT STARE INTO BEAM **CLASS 2 LASER PRODUCT** IEC 60825-1: 2014 P≤1mW; λ=670nm WITH 21 CFR 1040.10 AND 1040. R CONFORMANCE WITH IEC 608 ED. 3., AS DESCRIBED IN ASER NOTICE NO. 56, DATED MAY 8, 2019.

Laser label on the sensor cable

The sensors fall within laser class 3B. The laser is operated on a pulsed mode, the maximum optical power is  $\leq$  5 mW. The pulse frequency depends on the adjusted measuring rate (0.25 ... 10 kHz). The pulse duration of the peaks is regulated depending on the measuring rate and reflectivity of the target and can be 4 up to  $3995 \,\mu s$ .



LASER BADIATION AVOID DIRECT EYE EXPOSURE CLASS 3R LASER PRODUCT IEC 60825-1: 2014  $P \leq 5 \text{ mW}; \lambda = 658 \text{ nm}$ COMPLIES WITH 21 CFR 1040.10 AND 1040.11 EXCEPT FOR CONFORMANCE WITH IEC 60825-1 ED. 3., AS DESCRIBED IN LASER NOTICE NO. 56, DATED MAY 8, 2019.

Laser warning sign on the sensor housing

Laser labels on the sensor cable

Accordingly, the following applies: The accessible laser radiation is harmful to the eyes. Looking directly into the laser beam is harmful to the eyes with laser class 3R devices. Reflections of shiny or mirroring surfaces are also harmful to the eyes.

Class 3R laser sensors require a laser protection officer. Mark the laser area recognizable and everlasting. During operation the laser area has to be restricted and marked.



### **Intended Use**

The optoNCDT 1900 system is designed for use in industrial and laboratory areas. It is used for measuring displacement, distance and position as well as in in-process guality control and dimensional testing.

The sensor must only be operated within the limits specified in the technical data, see operating instructions, Chap. 3.3. The sensor must be used in such a way that no persons are endangered or machines and other material goods are damaged in the event of malfunction or total failure of the sensor. Take additional precautions for safety and damage prevention for safety-related applications.

### Warnings

- Switch off the sensor for cleaning and maintenance.

may cause harm.

Connect the power supply according to the safety regulations for electrical equipment. The supply voltage must not exceed the specified limits. > Risk of injury, damage to or destruction of the sensor.

media (detergents, cooling emulsions). > Damage to or destruction of the sensor

> Damage to or destruction of the sensor, failure of the measuring device.

# **Proper Environment**

- Optical inputs are excluded from protection class. Contamination leads to impairment or failure of the function.
- Temperature range
- Operation:
- Storage:
- Humidity







# Assembly Instructions optoNCDT 1900 / 1900LL

- Avoid unnecessary laser radiation to be exposed to the human body.
- Switch off the sensor for system maintenance and repair if the sensor is integrated into a sys-

Caution - use of controls or adjustments or performance of procedures other than those specified

- Avoid constant exposure of the sensor to splashes of water. Avoid exposure of sensor to aggressive
- Avoid shock and vibration to the sensor. Protect the sensor cable against damage.

- Protection class: IP67 (applies only when the sensor cable is plugged in)

```
0 ... +50 °C (+32 ... +122 °F)
-20 ... +70 °C (-4 ... +158 °F)
5 ... 95 % (non-condensing)
```

#### Switch on the Laser



## **Analog Output**

Current output 4 ... 20 mA or Voltage output 0 ... 5 V or 0 ... 10 V







Current output

 $atV_{.} = 11V$ 

 $C_{.} \leq 33 \text{ nF}$ 

 $R_{\rm p}$  max. = 250 Ohm



The current output may not be continuously operated in short-circuit operation without load resistor. This would lead to thermal overload and thus to the automatic overload cut-off of the output.

Analog output Pin 1,  $R_{\rm B} < (V_{\perp} - 6 \text{ V}) / 20 \text{ mA}$ coaxial inner conductor, white

> AGND Pin 2. screenina



## Multi-Function Input

The multi-function input enables triggering, zero setting/mastering and teaching. The function depends on the programming of the input and on the timing of the input signal.

The inputs are not electrically isolated. The maximum switching frequency is 10 kHz.



24 V logic (HTL): Low  $\leq$  3 V; High  $\geq$  8 V (max 30 V) 5 V logic (TTL): Low  $\leq$  0.8 V; High  $\geq$  2 V internal pull-up resistor, an open input is detected as High.

### RS422 Connection with USB Converter IF2001/USB

Cross the lines for connections between sensor and PC.

Disconnect or connect the D-sub connection between RS422 and USB converter when the sensor is disconnected from power supply only.

Senso	or	End device (converter)		
17-pin cable connector	Sensor cable	Type IF2001/USB from MICRO-EPSILON		
Tx + (Pin 8)	Gray	Rx +		
Tx - (Pin 15)	Pink	Rx -		
Rx + (Pin 9)	Green	Tx +		
Rx - (Pin 16)	Yellow	Tx -		
GND (Pin 14)	Blue	GND		
Laser On (Pin 3)	Black	Laser ON		

1000	24VDC GND Laser ON Multifunction Switch 1 Switch 2	RS422/USB Converter	24VDC GND Laser ON tuttifunction Switch 1 Switch 2 Rx -	a subscription
	USB	Status	Rx + Tx - Tx +	

Symmetric differential signals acc. to EIA-422, not electrically isolated from supply voltage. Use a shielded cable with twisted cores e.g. PC1900-x.

## **Quick Guide**

## Components



Connect the input to GND to trigger the function.

# **Initial Operation**



Signal quality

Median: 9

Inactive

## Access via Web Interface

Interactive web pages for programming the sensor now appear in the web browser. The sensor is active and supplies measurement values. The ongoing measurement can be operated by means of function buttons in the area Measurement chart.

- Connect the sensor to a PC/notebook via a RS422 connector. Connect The sensorthe supply voltage. TOOL program is available at https://
- Start the program sensorTOOL.
- Click the Sensor button.
- The program searches for connected ILD1900 sensors on available interfaces download/soft-

Select the desired sensor. Click on the button Open Website.



Select a Measuring Rate

**Go to the menu** Settings > Data recording > Measuring rate.

Start with a medium measuring rate. Select a measuring rate from the list. Confirm with Apply.

## Select an Interface

www.micro-epsi-

lon.com/service/

➡ Go to the menu Settings > Outputs > Output interface.

Defines which interface is used for output of measured values. Parallel output of measured values via multiple channels is not possible. RS422 and analog output cannot be operated simultaneously. While using the web interface, the output is switched off via RS422.

# **Place Target**

Position the target (measuring object) as much as possible in the midrange.



The State LED on the sensor indicates the position of the target to the sensor.

LED	Color		Labeling	Meaning	
	0	off	Laser off	Laser beam is switched off	
	green In range Target within measuring range	Target within measuring range			
State		yellow	w Midrange Target within the midrange	Target within the midrange	
		red	Error	Target outside the measuring range, too low reflection	

## Store the Settings

Go to the menu Settings > System settings > Load & Stores or click the Save settings button.

Read the detailed operating instructions before using the sensor. The manual is available online on www.micro-epsilon.com/download/manuals/man--optoNCDT-1900--en.pdf

MICRO-EPSILON MESSTECHNIK GmbH & Co. KG Koenigbacher Str. 15 • 94496 Ortenburg / Germany Tel. +49 (0) 8542 / 168-0 • Fax +49 (0) 8542 / 168-90 info@micro-epsilon.com • www.micro-epsilon.com Your local contact: www.micro-epsilon.com/contact/worldwide/

In the top navigation bar other functions (settings, measurement chart etc.) are available.

The appearance of the websites can change dependent on the functions. Each page contains descriptions of parameters and tips for filling the website.

